

ATTENTION: READ THIS



These chains are made with aggressive cutters for use only in mechanical processing applications. They can cause high kickback or other unexpected reactions in hand held equipment. High chain speed presents the risk of thrown pieces in the event of breakage or chain derailment. Use only on properly guarded machinery. Install and maintain these products according to manufacturers instructions.